



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program February 3, 2010

Reviewed: 

<b>Mine Name:</b> West Side Mine	<b>Permit Number:</b> S/035/0032
<b>Operator Name:</b> DJN Rockwalls	<b>Inspection Date:</b> October 27, 2009
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 10:00 am
<b>Other Participants:</b> none	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcemen
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>


**Bond Renewal Date:** 04-06-2006 **Bond Amount:** \$8,000 **Permit fee** is delinquent from 2008 to 2009, the total due is \$300

**Purpose of Inspection:** Routine annual Inspection. This site was inspected as a small mine site on 10/16/2008

**Inspection Summary:** There has been no work at this site since the annual inspection last year. A small pit is still open.

Photos were taken to document site conditions.

**Conclusions and Recommendations:** The site had good regenerative growth with native plants in the area. Any re-vegetation should not be difficult to achieve. Concurrent reclamation is recommended for any disturbances that can be reclaimed (i.e. contouring, seeding, etc.). Operator needs to pay annual fees. Operator needs to stockpile topsoil for reclamation. Delinquent fees need to be paid. DOGM will continue to monitor this site until these issues are resolved. Operator has 30 days to comply with all local, state and federal rules.

**Inspector's Signature** 

LAH:vs

cc: Shane Nay

O:\M035-SaltLake\S350032-DJN\inspections\Insp-02062010.doc







Area to be graded



Area to be graded

